0.00

Memo

\*120\*

**Quality Control** 

QC

Work Order ID 113496 \*113496\* Page 2 February-19-14 8:40:40 AM Item ID: D3646-3 Accept \*N900040100\* Setup Start **Revision ID:** Stop **Item Name:** Arm 2/19/14 \*6\* **Start Date:** Start Qty: 6.00 **Cust Item ID:** Req'd Oty: 6.00 Required Date: 3/05/14 \*6\* **Customer:** Reference: Run Start Date: **Approvals:** Process Plan: Date: **Tooling:** Stop QC: SPC (Y/N): Date: Date: Sequence ID/ **Operation** Tool ID Tool # Plan Set Up/ Accept Reject Reject Insp. **Work Center ID** Number **Description** Code Otv Oty Stamp **Run Hours** Black Sandtex(Ref:4.3.5.7) per QSI005 4.3 130 0.00 ( \$ 14-3.31. \*130\* Powdercoat 0.00 Memo OVEN TEMPERATURE: **Powder Coating** FINISH TIME: 140 QC3- Inspect Part Finish 0.00 6x d 11 4103/3, \*140\* OC 0.00 Memo **Quality Control** Identify as per dwg & Stock Location 150 6x 14-4-1 \*150\* Packaging 0.00 Memo

Packaging

26 0.80

-

M.

16.1999


3


200


125513

m126922

m128084









DART AERO	JSPAC		AEROSP.						
Description:	ARW	1.			Work Order	: 113496			
Inspection Drawing:	D36	46	Rev:	ے	Part Number	D3646-3			
INSPECTION SHEET									
Drawing Dimension	Tolerance				Method of Inspection	Comments			
26,50	±.030		V		5-Fab-07				
5,75	±.030		レ		1 ( -67				
1501	1%	15.0	V		11 -05				
45°	1%	450	V		1 - 05				
2,50	±,030	30°	V		11-07				
30°	l%	30	V		11 - 05				
			ļ						
			ļ	ļ		<u></u>			
			<u> </u>	-					
			<u> </u>						
				ļ					
			ļ						
		· · · · · · · · · · · · · · · · · · ·							
						······································			
			·						
		<u> </u>							
					·				
i									

·	DAS					
Measured by:	Checked By: 30 9-89	QC inspector:	Engineering Approval (if necessa			
Date 14-03-26	Date 14/13/26	Date 14/3/26	Date			